

 3M Australia Pty Limited

 Building A, 1 Rivett Road

 North Ryde, NSW 2113

 Phone:
 +61 2 9498 9333

 Fax:
 +61 2 9498 9666

 Web:
 3M.com.au

Product Information: 136 136 ABN 90 000 100 096 23 October 2019

UPDATE: STOP USE AND RECALL NOTIFICATION IMMEDIATE ACTION REQUIRED

To: Valued Customer

Subject: 3M[™] 9322A+ Respirator

This is an update to the previously issued "Safety Alert Notice", dated 9 October 2019.

3M Personal Safety now announces an immediate Stop Use and Product Recall of the 3M[™] 9322A+ respirators. Due to the lack of full adhesive application, the nose foam may separate from the top panel of the 3M[™] 9322A+ respirators. 3M has determined that affected respirators may not meet its expected performance.

This Stop Use and Recall only affects products with the following batch details shown on the outer shipper, on the individual box and on the individual respirators.

Product Name	Product Code:	ID number	Lot No:
Aura™ 9322A+ FFP2 Respirator	9322A+	XA010017854	See below table

Affected lot numbers:

Lot R19132 5 001	Lot R19131 5 001	Lot R19131 5 002
Lot R19131 5 003	Lot R19131 5 004	Lot R19131 5 005
Lot R19131 5 006	Lot R19131 5 007	Lot R19131 5 008
Lot R19130 5 008		

The lot code of the product can be found;

- 1. On the bottom right-hand side of the 3M shipper case label;
- 2. On the bottom left hand corner for the individual box; and
- 3. On the individual respirators





Shipper carton

Individual box



Individual Respirator

Foam separating from the top panel of respirator



If you have any of the affected products, please complete the attached "Stock Return Form" and email the form to your distributor together with an image of the batch number for replacement stock/credit.

3M sincerely regrets any inconvenience caused. Corrective actions are underway to prevent any re-occurrence of this issue.

Yours sincerely,

Balbir Blassey

3M ANZ Head of technical