

# Product Safety Recall

## YAMAHA PORTABLE GENERATOR EF2000iS



### Affected Range

7PB 0329803 ~ 7PB 0330916 - 2018

7PB 5080473 ~ 7PB 5080496 - 2019

### CORRECTIVE ACTION FOR FUEL TANK CRACKING

**DEFECT** The moulded area of the fuel tank to which the fuel valve is mounted was moulded at the incorrect temperature.

**HAZARDS** The tank material to be too brittle allowing the tank to crack. If the fuel tank cracks, fuel could leak, increasing the risk of fire which could result in severe injury or death

**REMEDY** Yamaha recommends that consumers do not operate their affected generator until this modification is performed.

The Yamaha Retailer will replace the fuel tank with one that has been correctly moulded.

For details of your local retailer please call 1300 735 440 or visit [www.generatoryamaha.com.au/where-to-buy/](http://www.generatoryamaha.com.au/where-to-buy/)

[www.generatoryamaha.com.au](http://www.generatoryamaha.com.au)

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information